To: Christoph Goss[christoph.goss@deereault.com]; Way, Steven[way.steven@epa.gov]; Matt

Francis[m.francis@erllc.com]; Griswold, Hays[Griswold.Hays@epa.gov]

From: Byron Hartman

Sent: Tue 11/17/2015 5:00:13 PM

Subject: RE: Gold King Update - Deere/Ault Steel set installation inspection

I think that would work for us. I will talk to HW. I'm pretty sure they will have the steel sets in by then.

From: Christoph Goss [mailto:christoph.goss@deereault.com]

Sent: Tuesday, November 17, 2015 9:23 AM

To: Way, Steven <way.steven@epa.gov>; Matt Francis <m.francis@erllc.com>; Byron Hartman

<b.hartman@erllc.com>; Griswold, Hays <Griswold.Hays@epa.gov>

Subject: RE: Gold King Update - Deere/Ault Steel set installation inspection

I could drive down Wednesday 12/2 and return on Friday 12/4. Would that be ok with people's schedules?

Christoph

From: Way, Steven [mailto:way.steven@epa.gov]
Sent: Tuesday, November 17, 2015 9:18 AM

To: Christoph Goss <christoph.goss@deereault.com>; Matt Francis <m.francis@erllc.com>;

Byron Hartman (b.hartman@erllc.com) <b.hartman@erllc.com>; Griswold, Hays

< Griswold. Hays@epa.gov>

Subject: RE: Gold King Update - Deere/Ault Steel set installation inspection

Byron and Christoph,

Please arrange for a field inspection of the Steel set installation – in particular related to the

planned installation of the flow control fabrication and installation. It would likely be appropriate to make plans for this during the week of 11/30. Let me know your ability to perform that task.
Thank you,
Steve
Steven Way
Federal On-Scene Coordinator
Emergency Response Unit
US EPA - Region 8
1595 Wynkoop Street
Denver, CO 80202
Office: 303-312-6723
From: Christoph Goss [mailto:christoph.goss@deereault.com] Sent: Thursday, November 05, 2015 7:49 AM To: Way, Steven; Matt Francis; Byron Hartman (b.hartman@erllc.com); Griswold, Hays; Ray Eldridge Subject: RE: Gold King Budget Update - Deere/Ault
We agree and can provide the qualified staff from our Boise office. The budget update that I sent out yesterday includes the prefabrication meeting on Tuesday and 2.5 days on site during installation. We can discuss installation time and additional shop visits during the call.

Christoph

From: Way, Steven [mailto:way.steven@epa.gov] Sent: Thursday, November 05, 2015 7:32 AM **To:** Christoph Goss <<u>christoph.goss@deereault.com</u>>; Matt Francis <<u>m.francis@erllc.com</u>>; Byron Hartman (<u>b.hartman@erllc.com</u>) <<u>b.hartman@erllc.com</u>>; Griswold, Hays <Griswold.Hays@epa.gov> Subject: RE: Gold King Budget Update - Deere/Ault Matt and Christoph, It is preferred that we someone form Deere and Ault be onsite to inspect the Flow Control Structure before delivery and during installation. Please let me know your thoughts and ability to provide that coverage. Thank you, Steve Steven Way Federal On-Scene Coordinator **Emergency Response Unit** US EPA - Region 8 1595 Wynkoop Street Denver, CO 80202

Office: 303-312-6723

From: Christoph Goss [mailto:christoph.goss@deereault.com]

Sent: Wednesday, November 04, 2015 5:17 PM

To: Matt Francis; Way, Steven; Byron Hartman (b.hartman@erllc.com)

Subject: Gold King Budget Update

Hi Steve, Matt, and Byron

Attached is the weekly budget update and projection. I adjusted the schedule per our conference call on Tuesday. As usual, numbers through last Friday are actual. The rest are estimated/projected.

Christoph

Christoph Goss, PhD, PE

Civil Engineer, Principal

Deere & Ault Consultants Inc.

600 S. Airport Rd. Bldg A Suite 205

Longmont, CO 80503

USA

Tel: 303.651.1468

Fax: 303.651.1469

Mobile: 720.560.1458

Christoph.goss@deereault.com

www.deereault.com

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.